



Front View



Loose/broken/delaminated
 Damage/wear/hole

Previous repair
 Replaced piece


Rear View



Missing
 Spindles not original to desk


Add-ons
 Inscriptions

Right Side




- | | |
|---|---|
| ■ Loose/broken/delaminated | ■ Previous repair |
| ■ Damage/wear/hole | ■ Replaced piece |

Left Side



- | | |
|---|---|
| ■ Missing | ■ Add-ons |
| ■ Spindles not original to desk | ■ Inscriptions |

Top



Loose/broken/delaminated

Damage/wear/hole

Previous repair

Replaced piece


Missing

Spindles not original to desk

Add-ons

Inscriptions


Bottom



Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece

Bottom







Missing
Spindles not original to desk



Add-ons
Inscriptions



Drawer Front, Outer Surface



Rear Surface of Drawer Front




 Loose/broken/delaminated
 Damage/wear/hole

 Previous repair
 Replaced piece


 Missing
 Spindles not original to desk

 Add-ons
 Inscriptions

Inside Surface of Left Drawer Side





Inside Surface of Right Drawer Side





 Loose/broken/delaminated


 Damage/wear/hole


 Previous repair

 Replaced piece

 Missing

 Spindles not original to desk


 Add-ons


 Inscriptions


Rear Surface of Drawer Back




Front Surface of Drawer Back





 Loose/broken/delaminated

 Damage/wear/hole


 Previous repair

 Replaced piece

 Missing



 Spindles not original to desk

 Add-ons

 Inscriptions

Upper Surface of Drawer Bottom


Lower Surface of Drawer Bottom





 Loose/broken/delaminated


 Previous repair

 Damage/wear/hole

 Replaced piece

 Missing



 Add-ons

 Spindles not original to desk

 Inscriptions

Outside Surface, Right Drawer Side


Outside Surface, Left Drawer Side




 Loose/broken/delaminated


 Damage/wear/hole


 Previous repair

 Replaced piece

 Missing

 Spindles not original to desk

 Add-ons

 Inscriptions